

Fig. 2




Fig. 3




Fig. 4




Fig. 5




Fig. 6

(A)

S1	
POSITION OF REF. POINT	X1, Y1
CORRECTION ANGLE $\theta$	- 0.1 DEG.
NUMBER OF SX	3
GAP BETWEEN SX	15mm
NUMBER OF SY	1
GAP BETWEEN SY	7mm

(B)

S2	
POSITION OF REF. POINT	X2, Y2
CORRECTION ANGLE $\theta$	- 0.2 DEG.
NUMBER OF SX	3
GAP BETWEEN SX	15mm
NUMBER OF SY	1
GAP BETWEEN SY	7mm

(C)

S3	
POSITION OF REF. POINT	X3, Y3
CORRECTION ANGLE $\theta$	- 0.3 DEG.
NUMBER OF SX	3
GAP BETWEEN SX	15mm
NUMBER OF SY	1
GAP BETWEEN SY	7mm

Fig. 7

(A)

S1	
CPS	COORDINATE
S1 - 1	x1, y1
S1 - 2	x1, y1 + 15
S1 - 3	x1, y1 + 30
S1 - 4	x1, y1 + 45
S1 - 5	x1 + 7, y1
S1 - 6	x1 + 7, y1 + 15
S1 - 7	x1 + 7, y1 + 30
S1 - 8	x1 + 7, y1 + 45

(B)

S2	
CPS	COORDINATE
S2 - 1	x2, y2
S2 - 2	x2, y2 + 15
S2 - 3	x2, y2 + 30
S2 - 4	x2, y2 + 45
S2 - 5	x2 + 7, y2
S2 - 6	x2 + 7, y2 + 15
S2 - 7	x2 + 7, y2 + 30
S2 - 8	x2 + 7, y2 + 45

(C)

S3	
CPS	COORDINATE
S3 - 1	x3, y3
S3 - 2	x3, y3 + 15
S3 - 3	x3, y3 + 30
S3 - 4	x3, y3 + 45
S3 - 5	x3 + 7, y3
S3 - 6	x3 + 7, y3 + 15
S3 - 7	x3 + 7, y3 + 30
S3 - 8	x3 + 7, y3 + 45